

Norman H. Bangerter Governor Dee C. Hansen Executive Director Dianne R. Nielson, Ph.D.

3 Triad Center, Suite 350

## DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple

INSPECTION REPORT

Dianno	Executive Director R. Nielson, Ph.D. Salt Lake City, Utah 84180-1203  Partial: XX Complete: Exploration									
Dianne	Division Director 801-538-5340 Inspection Date/Time: May 19, 1993/09:00am-01:00pm									
	Date of Last Inspection: April 7, 1993									
Mir	ne Name: Skyline Mine County: Carbon Permit Number: ACT/007/005									
Per	rmittee and/or Operator's Name: Coastal States Energy/Utah Fuel									
Bus	siness Address: P. O. Box 719, Helper, UT 84527									
Typ	pe of Mining Activity: Underground XX Surface Prep. Plant Other									
Ofi	ficials(s): State: <u>Stephen J. Demczak Company: Keith Zobell</u>									
Fed	deral Official(s): Weather Conditions: Warm 60's									
Existing Acres:Permitted-7067.11 Disturbed-62.08 Regraded-Seeded- Bonded-62.41										
Increased/Decreased: PermittedDisturbedRegradedSeededBonded										
Status: _Exploration/ X Active/ _Inactive/ _Temp Cessation/ _Bond Forfeiture										
F	Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)									
-	reary									
	REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS									
Inst	ructions									
	Substantiate the elements on this inspection by checking the appropriate performance standard.									
-	a. For complete inspections provide narrative justification for any elements not fully inspected unless									
	element is not appropriate to the site, in which case check N/A.									
	b. For partial inspections check only the elements evaluated.									
2.	Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard									
	listed below.									
3.	Reference any narratives written in conjunction with this inspection at the appropriate performance standard									
	listed below.									
4.	Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and									
	amendments.									
,	EVALUATED N/A COMMENTS NOV/ENF									
	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE [ ] [ ] [ ]									
	SIGNS AND MARKERS  [ ] [ ] [ ]  TOPSOIL  [XX] [ ]  [XX] [ ]									
3. 4.	TOPSOIL HYDROLOGIC BALANCE:  [XX] [ ] [XX] [ ]									
h.	DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS  [XX] [ ] [ XX] [ ]  [ ] [ ] [ ]									
G.	OTHER SEDIMENT CONTROL MEASURES [XX] [ ] [XX] [ ]									
d.										
	WATER MONITORING         [ ]									
	EXPLOSIVES [1] [1] [1]									
	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES [ ] [ ] [ ]									
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS [XX] [ ] [XX] [ ]									
8.	NONCOAL WASTE									
9.	PROTECTION OF FISH, WILDLIFE AND									
	RELATED ENVIRONMENTAL VALUES [ ] [ ] [ ]									
	SLIDES AND OTHER DAMAGE									
	SLIDES AND OTHER DAMAGE       [ ] [ ] [ ]       [ ]									
	BACKFILLING AND GRADING  [ ] [ ] [ ]									
13.	REVEGETATION [] [] []									
14.	SUBSIDENCE CONTROL [ ] [ ] [ ]									
15.	CESSATION OF OPERATIONS [ ] [ ] [ ]									
	ROADS:									
	CONSTRUCTION/MAINTENANCE/SURFACING [ ] [ ] [ ]									
b.										
18.	OTHER TRANSPORTATION FACILITIES  [ ] [ ] [ ]  SUPPORT FACILITIES/UTILITY INSTALLATIONS [ ] [ ] [ ]									
	AVS CHECK (4th Quarter-April, May, June)									
20.	AVS CHECK (4th Quarter-April, May, June)  [ ] [ ] [ ]  AIR QUALITY PERMIT [ ]									
	BONDING & INSURANCE									

# INSPECTION REPORT (Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: May 19, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

#### 3. Topsoil -

The majority of the snow has melted off the topsoil piles at the Skyline mine site. The topsoil piles at the loadout have a high concentration of grasses and no signs of erosion could be seen. The possibility exists that some of the topsoil piles on the property could eliminate the requirement of having straw bales as a control measure for erosion. The decision would have to be made jointly by the operator and a soil specialist at DOGM.

#### 4a. Diversion -

Several of the diversions and culverts were re-graded and cleaned of sediment from the melting snows.

### 4b. Other Sediment Control Measures

The pump house next to the state road could have a change out of straw bales between the creek and pump house. Certain bales are starting to deteriorate due to the winter snow. Operator has committed to change out the bales.

### 7. Refuse Piles

The refuse pile was inspected and the drainage ditch could be partly re-graded in one area but careful not to dig into the toe of the hillside until ground becomes less saturated.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed	to:	Coastal	States	Energy/Utah	Fuel,	Keith	Zobell	-11
Mailed	to:	Bernie	Freema	n (OSM)				
Given	to:_	Joe Hel:	frich (	DOGM)				
Filed	to:	Price F:	ield Of	fice				
Date:	Mav	21. 1993				$\overline{}$		

Inspector's Signature and Number:

Steplen J. Demozak

#29